

NATIONAL PARK SERVICE, WESTERN REGION
HISTORIC AMERICAN ENGINEERING RECORD

HAER.
CAL.
18-LOCAL,
52-

INDEX TO PHOTOGRAPHS

Goodyear Rubber Company
6701 South Central Avenue
Los Angeles
Los Angeles County
California

HAER No. CA-13

Tom Zimmerman, Photographer, October 1980

NOTE: All negatives are 2-1/4" x 2-1/4"

CA-13-1	BUILDING 35, FACADE
CA-13-2	BUILDING 35, VIEW FROM ACROSS STREET
CA-13-3	BUILDING 35, SIDE VIEW INCLUDING GUARDHOUSE BUILDING 63
CA-13-4	BUILDING 62, GUARDHOUSE
CA-13-5	BUILDING 31, ENTRANCE FACADE
CA-13-6	BUILDING 31, VIEW OF ENTRANCE SHOWING NEWS SIGN
CA-13-7	BUILDING 31, VIEW OF ENTRANCE
CA-13-8	BUILDING 31, ENTRANCE, VIEW OF FRONT STEPS AND DOOR
CA-13-9	BUILDING 31, DOORWAY DETAIL, ENTRANCE LOBBY
CA-13-10	BUILDING 31, MAIN FLOOR LABORATORY, INTERIOR VIEW SHOWING DETAIL OF WINDOW AND TILE WALL
CA-13-11	BUILDING 31, KITCHEN, MAIN FLOOR INTERIOR
CA-13-12	BUILDING 31, MAIN FLOOR LABORATORY, INTERIOR
CA-13-13	BUILDING 31, SECOND LEVEL INTERIOR
CA-13-14	BUILDING 31, SECOND LEVEL INTERIOR, WINDOWS ON LEFT
CA-13-15	BUILDING 31, THIRD LEVEL INTERIOR
CA-13-16	BUILDING 31, THIRD FLOOR OFFICES, INTERIOR
CA-13-17	BUILDING 31, DETAIL, THIRD FLOOR OFFICES, INTERIOR
CA-13-18	BUILDING 32A, REAR VIEW
CA-13-19	BUILDINGS 31, 32A, 34, REAR VIEW

Goodyear Rubber Company
Index to Photographs
HAER No. CA-13
(Page 2)

CA-13-20	BRIDGES BETWEEN BUILDINGS 34 AND 41
CA-13-21	BUILDING 34, THIRD FLOOR INTERIOR
CA-13-22	BUILDING 34, SECOND FLOOR INTERIOR
CA-13-23	EAST BRIDGE, BUILDINGS 41 TO 31, INTERIOR
CA-13-24	BUILDING 41, FACADE
CA-13-25	BUILDING 41, FACADE CLOSE UP
CA-13-26	BUILDING 41, NORTH ELEVATION
CA-13-27	BUILDING 41, REAR AND SOUTH ELEVATION
CA-13-28	BUILDING 41, INTERIOR
CA-13-29	BUILDING 41, DETAIL, ELEVATOR MACHINERY, INTERIOR
CA-13-30	BUILDING 6, EACADE
CA-13-31	BUILDING 6, SOUTH ELEVATION
CA-13-32	BUILDING 6, MAIN FLOOR, INTERIOR
CA-13-33	BUILDING 6, SECOND FLOOR, INTERIOR
CA-13-34	BUILDING 6, SECOND FLOOR, POST DETAIL, INTERIOR
CA-13-35	BUILDING 6, SECOND FLOOR, MACHINERY DETAIL, INTERIOR
CA-13-36	BUILDING 6, SECOND FLOOR, MACHINERY DETAIL, INTERIOR
CA-13-37	BUILDING 6, THIRD FLOOR, INTERIOR
CA-13-38	BUILDING 4, CEMENT HOUSE, NORTH ELEVATION
CA-13-39	BUILDING 4, CEMENT HOUSE, SECOND FLOOR, INTERIOR
CA-13-40	BUILDING 4, CEMENT HOUSE, MAIN FLOOR, INTERIOR
CA-13-41	BUILDING 5, MACHINE SHOP, SOUTH ELEVATION
CA-13-42	BUILDING 5, MACHINE SHOP, INTERIOR
CA-13-43	BUILDING 5, MACHINE SHOP, INTERIOR DETAIL
CA-13-44	BUILDINGS 1, 2, 3, POWER HOUSE, EACADE

Goodyear Pubber Company
Index to Photographs
HAER No. CA-13
(Page 3)

CA-13-45	BUILDINGS 1, 2, 3, POWEPHOUSE, SOUTH ELEVATION
CA-13-46	BUILDING 2, POWER HOUSE, BOILER POOM, INTEPIOP
CA-13-47	BUILDING 2, POWER HOUSE, MAIN FLOOP, INTERIOP
CA-13-48	BUILDING 2, POWER HOUSE, PUMP HOUSE, INTERIOP
CA-13-49	BUILDING 2, POWER HOUSE, PUMP HOUSE, INTERIOR DETAIL
CA-13-50	BUILDING 54, LATEX STOPAGE
CA-13-51	BUILDING 55, RESILIOMETER TEST
CA-13-52	BUILDING 52, REAP
CA-13-53	BUILDING 51, GARAGE
CA-13-54	BUILDING 57, AIPSHIP DOCK, CLOSER VIEW
CA-13-55	BUILDING 57, AIRSHIP DOCK
CA-13-56	BUILDING 57, AIPSHIP DOCK, INTERIOR
CA-13-57	BUILDING 59, SYNTHETIC PUBBEP STORAGE
CA-13-58	BUILDING 7, WEST FLEVATION
CA-13-59	BUILDING 7, EAST ELEVATION
CA-13-60	WATEP TANK AND PUMP HOUSE
CA-13-61	CAPBON BLACK TOWER